19th Annual Meeting of the Society for the Preservation of Natural History Collections Museum SOS: Strategies for Emergency Response and Salvage

May 14, 2004



Recovery & Renovation of the Pentagon following 9/11:

The Phoenix Project



Brett D. Eaton
Information & Communications Officer
Washington Headquarters Services



ORIGINAL CONSTRUCTION



September 11, 1941 to January 15, 1943

Completed in 16 months by working three 5,000-man shifts around the clock.





THE EARLY YEARS




Minimal electrical, communications and HVAC requirements/capacity; Open-bay office environment; Flooding conditions.















A SMALL CITY



The Pentagon has never undergone a major renovation.



34 acres 6.5 million sq. ft. 3 Empire State Bldgs. 7,748 windows 17.5 miles of corridors 25,000 personnel 1,000,000 calls per day Police force Metro station Fire Station **Health Facilities** Post Office

Mini-mall

Heliport



WORKING CONDITIONS



Inefficient office space, unreliable utilities, non-code compliant...













HAZARDOUS WORKING CONDITIONS

FENTAGON RENDATIONA CONSTRUCTION

PCBs, Asbestos, Mercury, Lead...



"The Pentagon is a classic example of "disinvestment" in federal buildings. For at least 10 years, needed major repairs and alterations to the Pentagon have been deferred. DoD officials, beginning in 1985, sought operational control of the building."

GAO Report to the Chairman, Subcommittee on Public Buildings and Grounds, Committee on Public Works and Transportation, House of Representatives

May 1991

GAO/GGD-91-57











PENTAGON RENOVATION



- Relocate 5,000 people
- Demo, Abate & Reconstruct 1 million sq. feet
- Improve safety, reliability, efficiency





·Blast Resistant Windows ·Structural Steel Tubes ·Geotechnical Mesh



•Replacement of Exterior High Pressure Water Lines



•Fire Sprinklers
•Building Code Compliance



•Monitoring & Control Systems •Building Operations

Building Operations
Command Center



Automated Smoke Doors



SECURITY INITIATIVES





Pentagon Remote Delivery Facility









Pentagon Metro Entrance Facility










ANALYSIS




- 1.6 million sq. ft. of fire, water, smoke, mold damage
- 400,000 sq. ft of severe structural damage




















TOPPING OUT CEREMONY

April 5, 2002












LIMESTONE FAÇADE COMPLETE



June 11, 2002

4,000 slabs of limestone replaced









BEFORE & AFTER

September 11, 2001

September 11, 2002










BEFORE & AFTER

September 11, 2001

September 11, 2002









UNITED IN FREEDOM

September 11, 2002













PENREN CONTINUES



- Wedges 2-5 schedule advanced by four years completion mandated in 2010
- New Projects Added



- Pentagon Athletic Center
- · Road, Grounds & Security
- Command Communications Survivability Program
- Continuity of Operations
- Pentagon Conference and Logistics Center
- Alternate Command & Control Sites
- Pentagon Memorial







